

Olcayto Servis Hizmetleri

**REPAIR EXPERTISE FORM**

2017131681

August 26, 2017

Customer Information

120 34 014 030666  
EFE OTOMOTIV TUR. KUYUM.İNŞ.İTH.  
İHR. TİC. LTD. ŞTİ.

YAKUPLU MERMEZ MH. HÜRRIYET BLV. SKY  
GİRİŞİ K1 NO. 51  
BEYLİKDÜZÜ/İSTANBUL  
Phone:

Vehicle Information

Number plate : 34YN7047  
Brand : AUDI  
Type : Q7  
Model year : 2015  
Mileage : 30712  
Colour :  
Motor Number : CRT039550  
Chassis Number : WAUZZZ4M2GD01054

Insurance and Expert Information

Insurance company :  
Policy type :  
Policy number :  
Damage file number :

**BREAKDOWN OF LABORSHIP AND PARTS TO BE APPLIED ON THE VEHICLE SUBJECT TO EXPERTISE**

POS.	WORK-PART CODE	LABORSHIP/PART NO.	QUANTITY	UNIT PRICE	AMOUNT	DISCOUNT	
1	EGZ2	EXHAUST EMISSION	1.00	1.00	1.00		
TOTAL LABORSHIP:		,00 DISCOUNT	,00	0%	TOTAL NET:	0,00 DISCOUNT AMOUNT	,00
TOTAL PARTS:		1,00 DISCOUNT	,00	0%	TOTAL NET:	1,00	
TOTAL NET:		1,00 VAT:	0		EXPERTISE AMOUNT:	1,18	

EXPERTISE REMARKS:

10- EQOPED DEVICE HAS BEEN TESTED ON BEHALF OF IO- ENERGIES AG. THE VALUES ARE AS STATED BELOW.

• VALUES BEFORE APPLYING THE DEVICE

IDLE RUNNING (MIN.) 3000 REVOLUTIONS (MAX.)  
1<sup>ST</sup> MEASUREMENT 0.77 1<sup>ST</sup> MEASUREMENT 0.92  
2<sup>ND</sup> MEASUREMENT 0.86 2<sup>ND</sup> MEASUREMENT 0.91  
3<sup>RD</sup> MEASUREMENT 0.90 3<sup>RD</sup> MEASUREMENT 0.92  
AVERAGE 0.85 AVERAGE 0.91

• VALUES AFTER APPLYING THE DEVICE

IDLE RUNNING (MIN.) 3000 REVOLUTIONS (MAX.)  
1<sup>ST</sup> MEASUREMENT 0.65 1<sup>ST</sup> MEASUREMENT 0.66  
2<sup>ND</sup> MEASUREMENT 0.64 2<sup>ND</sup> MEASUREMENT 0.64  
3<sup>RD</sup> MEASUREMENT 0.65 3<sup>RD</sup> MEASUREMENT 0.70  
AVERAGE 0.65 AVERAGE 0.67

THE RESULT PROVIDES SAVING OF 25% IN AVERAGE.

DEVICE, BRAND: BILSA, MOD 2210 WINXP-K

COMPANY OWNER

OLCAY DÖNMEZ

-stamp and signature-

PROCESSED BY

UFUK BAŞ

-signature-

Atatürk Sanayi Sitesi 2. Kısım 11. Sok. No. 373 80670 Maslak / İSTANBUL

Tel : (0212) 276 55 50 Tel/Fax : (0212) 286 15 10 GSM: (0532) 232 84 24

e-mail: olcaytoBoschoutonet.com Maslak V.D. 3120038347



**OLCAYTO**  
**CAR SERVICE**  
Nispetiye DÖNMEZ Sic. No. 31855  
Atatürk Oto San. S. 2. Kısım 11. Sok.  
No. 373 Maslak / İSTANBUL  
Tel: (0212) 276 55 50  
Maslak V.D.: 3120038347

Atatürk Sanayi Sitesi 2. Kısım 11. Sok. No.373 80670 Maslak / İSTANBUL

Tel : (0212) 276 55 50 Tel/Fax : (0212) 286 15 10 GSM : (0532) 232 84 24

E-mail-olcaytoBoschoutonet.com.

Maslak V.D. 3120038347

**ONARIM EKSPERTİZ FORMU**

2017131681

26.08.2017  
Car Service**Müşteri bilgileri**

120 34 014 030666  
EFE OTOMOTİV TUR. KUYUM. İNŞ. İTH.  
İHR. TİC. LTD. ŞTİ.

YAKUPLI MERMEZ MH, HÜRRIYET BLV. SKY  
GİRİŞİ K1 NO 51  
BEYLİKDÜZÜ/İSTANBUL  
Tel:

**Araç bilgileri**

Plaka: : 34YN7047  
Markası: : AUDI  
Tipi: : Q7  
Model : 2015  
Kilometresi: : 30712  
Renk:  
Motor no: : CRT039550  
Şasi no: : WAUZZZ4M2GD01054

**Sigorta ve eksper bilgileri**

Sigorta şirketi:  
Poliçe türü:  
Poliçe no:  
Hasar dosya no:  
Eksper adı:

**EKSPERTİZİ YAPILAN ARACA, YAPILACAK İŞÇİLİKLER VE TAKILACAK PARÇALAR DÖKÜMÜ**

SIRA	İŞ-PARÇA KODU	İŞÇİLİK/PARÇA ADI	MİKTAR	BİRİM FİYAT	TUTAR	ISK.
1	EGZ2	EGZOZ EMİSYON	1,00	1,00	1,00	
İŞÇİLİK TOPLAMI:		,00 İNDİRİM	,00	%0 NET TOPLAM:	,00	İNDİRİM TOPLAMI: ,00
PARÇA TOPLAMI:		1,00 İNDİRİM	,00	%0 NET TOPLAM:	1,00	
NET TOPLAM:		1,00 KDV:	0	EKSPERTİZ TUTARI:	1,18	

**EKSPERTİZ NOTU :**

10- ENERGİES AG ADINA EQOPED CİHAZI TEST EDİLMİŞTİR DEĞERLERİ AŞAĞIDAKİ GİBİDİR

**• CİHAZ TAKILMADAN ÖNCEKİ DEĞERLER**

ROLANTİ ( MİN.) 3000 DEVİR ( MAX )  
1. ÖLÇÜM 0.77 1. ÖLÇÜM 0.92  
2. ÖLÇÜM 0.86 2. ÖLÇÜM .091  
3. ÖLÇÜM 0.90 3. ÖLÇÜM 0.92  
ORTALAMA 0.85 ORTALAMA 0.91

**• CİHAZ TAKILDIKTAN SONRAKİ DEĞERLER**

ROLANTİ ( MIN ) 3000 DEVİR ( MAX )  
1. ÖLÇÜM 0.65 1. ÖLÇÜM 0,66  
2. ÖLÇÜM 0.64 2. ÖLÇÜM 0.64  
3. ÖLÇÜM 0.65 3. ÖLÇÜM 0.70  
ORTALAMA 0.65 ORTALAMA 0.67

**SONUÇ ORTALAMA % 25 TASARRUF SAĞLAMAKTADIR.**

CİHAZ MARKA BİLSA MOD 2210 WINXP-K

FİRMA SAHİBİ  
OLCAY DÖNMEZİŞLEM YAPAN  
UFUK BAŞ